

HISTORIC AMERICAN BUILDINGS SURVEY

INDEX TO PHOTOGRAPHS

HABS
NH
9-SOMER,
1A-

17-19 Market Street (Mill Management Housing)
Somersworth
Strafford County
New Hampshire

HABS No. NH-123

Photographer: Ernest Gould

July 19, 1984

NH-123-1	SOUTH SIDE AND EAST FRONT
NH-123-2	EAST FRONT AND NORTH SIDE
NH-123-3	VIEW FROM SOUTHWEST
NH-123-4	VIEW FROM NORTHWEST
NH-123-5	SECOND FLOOR, SOUTHEAST CORNER ROOM, LOOKING WEST
NH-123-6	FIRST FLOOR, SOUTHEAST CORNER ROOM, DETAIL OF SOUTHEAST CORNER
NH-123-7	FIRSTS FLOOR, SOUTHEAST CORNER ROOM, LOOKING SOUTHWEST
NH-123-8	SECOND FLOOR, SOUTHWEST CORNER ROOM, LOOKING NORTHEAST
NH-123-9	FRIST FLOOR, NORTHEAST CORNER ROOM, LOOKING SOUTHWEST
NH-123-10	FIRST FLOOR, NORTH UNIT, CENTER ROOM, LOOKINC EAST